


## ELECTRICAL CONNECTIONS SUGGESTED

Electrical Power INPUT  
Single Phase - 220V – 15 Amp

Switch to turn on/off the vacuum fan.  
Avoid the noise when it is not necessary  
220V – 15 amp.

One female plug for laser machine:  
220V – 15 Amp.

One female plug for vacuum fan:  
220V – 15 Amp.



## EXAMPLES OF ELECTRICAL CONNECTIONS

The customer has to have to have at least two male plug until 240V – 15 Amps.

